



ITEM #	ITEM DESCRIPTION
1	7 MM CORRUGATED PANEL
2	1/4" X 2" SYP ALUM F-TRACK FLAT
3	1/4" X 2-1/2" DIA HEX HD TAPCON
4	2-1/2" S.S. MACHINE BOLT
5	1/4"-20 S.S. WING NUT
6	1/4" X 1-1/4" X 1/2" RUBBER WASHER




TEST SPECIMEN COMPLIES WITH THESE DETAILS. ANY DEVIATION IS NOTED.
REPORT NO. NCTL - 210 - 3193-1
TEST DATE: 10.12.05

EXTERIOR ELEVATION
7 MM CORRUGATED

GALLINA USA LLC
 245 EAST MADISON AVE.
 MILTON, VT 05553


PROJECT BY: JRM
 DATE: 10/27/05
 DRAWING NO.: 5
 SCALE: 1/4" = 1'-0"
 SHEET: 1 OF 2


PREPARED BY: PFC ENGINEERING, INC.
 PROJECT: BILL OF MATERIALS AND ELEVATION DETAILS



TEST SPECIMEN COMPLIES WITH THESE DETAILS. ANY DEVIATION IS NOTED. REPORT NO. NCTL - 210 - 3193-1 TEST DATE: 10-12-05

DESCRIZIONE: ARCOPLUS ONDA
 MATERIALE: POLICARBONATO 100%
 N. FILE: 2155.DWG
 DATA: 23.09.02
 AUTORE: [Logo]
 N. PROGETTO: 2155A
 N. DISCIPLINA: [Logo]





TEST SPECIMEN COMPLIES
WITH THESE DETAILS. ANY
DEVIATION IS NOTED.
REPORT NO. NCTL - 210 - 3193-1
TEST DATE: 10-12-05